


SKODA SUPERB COMBI: 1PZE899

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | TMBJG7NP1H7030920 | Versionname: | 1.6 CRTDI 88KW STYLE |
| First Registrationdate: | 18/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 156177 | Power Kw: | 88 |
| Bodytype: | | Body color: | White |
| Gearbox: | MAN 6 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2504 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Windows electric F | | Seats R heated | |
| Windows electric R | | Seats electric F L | |
| Cruise Control | | Central consol F | |
| Steering wheel multifunctional | | Luggage cover | |
| Seats F heated | | Front parking sensors | |
| Radio multimedia | | Rear parking sensors | |
| Type of headlighting | Headlighting Xenon | Type of Tow bar | No Tow bar |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/55/17/94 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|-----------------------------------|------|
| Total cost ex VAT | 0,00 |
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Roof, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |

