



SKODA Superb: 1HSC095

Vinnumber:	TMBJJ93T5F9021197	Versionname:	SUPERB COMBI GreenLine Elegance 105PK
First Registrationdate:	18/09/2014	Fiscalpower:	77
Expertise Mileage:	164172	Power Kw:	Dark Brown
Bodytype:		Body color:	Metalic
Gearbox:	MAN 6 VIT	Paint type:	Aluminium
Transmission:	Front	Rims summer:	OK
Fueltype:	Diesel	Oil level:	2825
Battery functioning:	Yes	Parking lot:	
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats R heated
Windows electric F	Seats electric F L
Windows electric R	Seats electric F R
Cruise Control	Sun Roof electric
Steering wheel multifunctional	Panoramic roof
Seats F heated	Central consol F
Radio multimedia	Luggage cover
Type of headlighting	Front parking sensors
Type of GPS	Rear parking sensors
Type of Lining	Type of Tow bar
Type of climate control	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1768,04
Door R R, Scratch(es), LI - Repair and paint (complete)	382,02



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

