



**VOLKSWAGEN Golf: 1HNG328**

Vinnumber:	<b>WVWZZZAUZFP533602</b>	Versionname:	<b>GOLF VAR Trendline 105PK</b>
First Registrationdate:	<b>27/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>84823</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>IN 5700 KM</b>	Parking lot:	<b>3305</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 T LightMetal</b>			
Summer tyres:	Fr.L. <b>Firestone: 5 mm</b>	Fr.R. <b>Firestone: 5 mm</b>	
	Re.L. <b>Michelin: 4 mm</b>	Re.R. <b>Michelin: 4 mm</b>	

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------


Total cost ex VAT	210,56
Bumper F R, Scratch(es), It - Spot repair	115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Chemical polution, 67 - Polish	0,00
--	------



Wing F R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Roof, Chemical polution, 67 - Polish	0,00
--------------------------------------	------



Wing F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display