



FORD FOCUS: 1LPU724

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WF05XXGCC5FU33498 | Versionname: | 1.5 TDCI 77KW S/S ECON 88G BUSINESS ED |
| First Registrationdate: | 9/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 90949 | Power Kw: | 77 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1306 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | Type of Tow bar |
| Steering wheel multifunctional | No Tow bar |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 215/55/16/97 W Steel | | | |
| Summer tyres: | Fr.L. | Other: 3 mm | Fr.R. | Other: 3 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|---|---------|
| Total cost ex VAT | 2215,06 |
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 308,20 |



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 231,80



Roof pillar L, Scratch(es), LI - Repair and paint (complete) 220,18



Reflector, Crack, E - Replace 64,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F R, Scratch(es), E - Replace 30,00



Roof pillar R, Scratch(es), LI - Repair and paint (complete) 220,18



Rear window, Scratch(es), E - Replace 370,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door seal F R, Deformed / Strained, E - Replace 54,00



Luggage space cover, Missing, E - Replace 80,00

