


RENAULT CLIO: 1LSD412

Vinnumber:	VF15R0J0A54168229	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	20/11/2015	Fiscalpower:	
Expertise Mileage:	95471	Power Kw:	66
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3433
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T None			
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1202,22
Bumper moulding F, Scratch(es), E - Replace	11,52



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror R complete, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Tailgate, Scratch(es), LI - Repair and paint (complete) 241,34



Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56

