



VOLVO XC90: ZG9853

Vinnumber:	YV1LFA4BCG1011801	Versionname:	2.0 D5 4WD GEARTRONIC MOMENTUM 7PL.
First Registrationdate:	6/08/2015	Fiscalpower:	
Expertise Mileage:	189583	Power Kw:	165
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1715
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage		Seats electric F L	
GPS storage	HD	Seats electric F R	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/19/105 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1630,16
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Scratch(es), Acceptable

0,00




Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)

115,56



Rear window, Scratch(es), E - Replace

420,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display


Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00



Wing trim R R, Scratch(es), Le - Replace and paint 120,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display