



**OPEL COMBO: 1VRJ390**

|                                    |                                 |              |               |
|------------------------------------|---------------------------------|--------------|---------------|
| Vinnumber:                         | <b>W0VEFBHWBKJ540386</b>        | Versionname: |               |
| First Registrationdate:            | <b>5/02/2019</b>                | Fiscalpower: |               |
| Expertise Mileage:                 | <b>4191</b>                     | Power Kw:    | <b>55</b>     |
| Bodytype:                          |                                 | Body color:  | <b>Black</b>  |
| Gearbox:                           | <b>MAN 5 VIT</b>                | Paint type:  | <b>Opaque</b> |
| Transmission:                      | <b>Front</b>                    | Rims summer: | <b>Steel</b>  |
| Fueltype:                          | <b>Diesel</b>                   | Oil level:   | <b>OK</b>     |
| Maintenance:                       | <b>NOT OK</b>                   | Parking lot: | <b>3120</b>   |
| Battery functioning:               | <b>Yes</b>                      |              |               |
| Number of doors:                   | <b>5</b>                        |              |               |
| Number of seats:                   | <b>2</b>                        |              |               |
| Number head rests:                 | <b>2</b>                        |              |               |
| Rims summer:                       | <b>Steel</b>                    |              |               |
| Category:                          | <b>Light Commercial Vehicle</b> |              |               |
| Oil level:                         | <b>OK</b>                       |              |               |
| Registration Certificate Car (BE): | <b>Yes</b>                      |              |               |

**Options**

|                                |                               |                      |
|--------------------------------|-------------------------------|----------------------|
| Windows electric F             |                               | Rear parking sensors |
| Cruise Control                 |                               |                      |
| Steering wheel multifunctional |                               |                      |
| Radio multimedia               |                               |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                      |
| Type of Lining                 | <b>Lining fabrics</b>         |                      |
| Type of climate control        | <b>Manual climate control</b> |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                             |       |                          |       |                          |
|-----------------------------|-------|--------------------------|-------|--------------------------|
| <b>195/65/15/92 H Steel</b> |       |                          |       |                          |
| Summer tyres:               | Fr.L. | <b>Continental: 5 mm</b> | Fr.R. | <b>Continental: 5 mm</b> |
|                             | Re.L. | <b>Continental: 6 mm</b> | Re.R. | <b>Continental: 6 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>110,64</b> |
|-------------------|---------------|

|                                   |             |
|-----------------------------------|-------------|
| Maintenance, Maintenance, Execute | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|                               |             |
|-------------------------------|-------------|
| Wing R L, Dent(s), Acceptable | <b>0,00</b> |
|-------------------------------|-------------|

*No pictures to display*

|                                     |               |
|-------------------------------------|---------------|
| Bumper R, Scratch(es), Smart repair | <b>110,64</b> |
|-------------------------------------|---------------|

