



VOLKSWAGEN TOURAN: 1LSU070

Vinnnumber:	WVGZZZ1TZGW524134	Versionname:	1.6 TDI SCR 81KW BMT TRENDLINE
First Registrationdate:	25/11/2015	Fiscalpower:	
Expertise Mileage:	144737	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1209
Maintenance:	28800KM OF 719DGN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
TV/DVD screen R		Panoramic roof	
GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/94 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 767,09

Seat cover F R, Stain, Cleaning 25,00



Door frame R R, Dent(s), It - Spot repair 115,56



Wing F R, Scratch(es), Acceptable 0,00



Seat cover R, Stain, Cleaning 25,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Trunk lid covering R, Scratch(es), Acceptable 0,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Door R R, Dent(s), PDR - Paintless dent repair 63,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



