



VOLVO XC90: SP7777

Vinnumber:	YV1LFBABDJ1326920	Versionname:	2.0 T8 4WD Geartronic R-Design 7PL
First Registrationdate:	2/11/2017	Fiscalpower:	
Expertise Mileage:	45141	Power Kw:	300
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3427
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Central consol F	
Type of headlighting	Headlighting LED	Luggage cover	
Type of GPS	GPS big screen color	Front parking sensors	
Type of Lining	Lining leather and alcantara	Rear parking sensors	
Type of climate control	Autom climate control	Type of Tow bar	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	275/45/20/110 V LightMetal			
	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	716,30
Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21




Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Chemical polution, Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wheel arch cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), E - Replace 104,00

