



VOLKSWAGEN TIGUAN: RY6548

Vinnumber:	WVGZZZ5NZHW823884	Versionname:	2.0 TDI BMT BMT 140KW DSG7 4WD HIGHLINE
First Registrationdate:	18/11/2016	Fiscalpower:	
Expertise Mileage:	175499	Power Kw:	140
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3724
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats R heated	
GPS storage		Seats electric F L	
GPS storage	SD	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	235/55/18/100 H LightMetal			
	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	63,00
-------------------	--------------

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), PDR - Paintless dent repair	63,00



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Bumper cover R M, Scratch(es), Acceptable	0,00
---	------

No pictures to display