



MERCEDES A: 1PUZ061

Vinnumber:	WDD1760121J532937	Versionname:	A 180 d BlueEFFICIENCY Edition
First Registrationdate:	26/09/2016	Fiscalpower:	
Expertise Mileage:	44463	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3601
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 V Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1977,26
Door frame R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), E - Replace	370,00



Wing R R, Bad repair, Acceptable

0,00



Wheel cover R R, Scratch(es), E - Replace

30,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace

30,00



Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Broken, Le - Replace and paint

735,00



Bumper R, Scratch(es), Acceptable

0,00

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

30,00



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Wheel cover F L, Scratch(es), E - Replace

30,00



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display