



CITROEN Berlingo: 1BNM524

Vinnumber:	VF77J9HP0BJ687613	Versionname:	BERLINGO 2PLC XTR FAP 92PK
First Registrationdate:	11/07/2011	Fiscalpower:	
Expertise Mileage:	132867	Power Kw:	68
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2413
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Panoramic roof
Windows electric F	Central consol F
Cruise Control	Luggage cover
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1098,58
Protection plate M, Deformed / Strained, E - Replace	74,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Smart repair

110,64



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,13



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Bonnet, Stone chip(s), Acceptable

0,00





Bumper F, Scratch(es), Smart repair

110,64



Roof, Dent(s), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair

0,00



Wheel cover R R, Scratch(es), E - Replace

22,50



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Door panel F L, Worn, Acceptable

0,00



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

22,50



Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	