


BMW X5: YM7996

Vinnumber:	WBAKS410500W61917	Versionname:	xDrive30d (190 kW)
First Registrationdate:	31/10/2017	Fiscalpower:	
Expertise Mileage:	178853	Power Kw:	190
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2810
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats F L ventilated
Windows electric F		Seats F R ventilated
Windows electric R		Sun Roof electric
Cruise Control		Panoramic roof
Steering wheel multifunctional		Central consol F
Seats F heated		Luggage cover
Type of headlighting	Headlighting LED	Front parking sensors
Type of GPS	GPS big screen color	Rear parking sensors
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/45/19/111 W LightMetal				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			869,92
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror glass L, Broken, E - Replace

21,60



Ignition key, Missing, E - Replace

150,00

No pictures to display