



**AUDI A1 SPORTBACK: 1LLU062**

Vinnumber:	<b>WAUZZZ8X1GB045639</b>	Versionname:	<b>1.6 TDI 85KW</b>
First Registrationdate:	<b>22/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>70321</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4822</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

Winter tyres:	<b>185/60/15/92 MS LightMetal</b>			
	Fr.L.	<b>Goodyear: 5 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>3141,29</b>
Alloy rim R L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing R R, Dent(s), PDR - Paintless dent repair			<b>63,00</b>



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Windscreen, Stone chip(s), Windscreen repair

58,80



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

342,56



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Boot cover, Broken, Forfeit

15,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Chemical pollution, LI - Repair and paint (complete)

232,06



Door R L, Dent(s) and scratch(es), Le - Replace and paint

786,33



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Chemical pollution, LI - Repair and paint (complete)

385,20



Bumper F, Crack, Le - Replace and paint

607,20



Wing F L, Dent(s), LI - Repair and paint (complete)

176,14

