


AUDI A3: 1HJK337

Vinnumber:	WAUZZZ8VXF028700	Versionname:	A3 SB Ambition 110PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	153892	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4228
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Rear parking sensors
GPS storage	SD	
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/94 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			911,91
Bumper R, Crack, Le - Replace and paint			0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Bad repair, LI - Repair and paint (complete)

0,00



Outer door handle F L, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s), It - Spot repair

115,56



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35



Boot cover, Missing, E - Replace

50,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Scratch(es), Acceptable

0,00

No pictures to display