


AUDI A4 AVANT: 1LUU057

Vinnumber:	WAUZZZ8K1FA187322	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	10/12/2015	Fiscalpower:	
Expertise Mileage:	114319	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3409
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	DVD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1640,32
Roof, Chemical polution, LI - Repair and paint (complete)	481,50



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper moulding F L, Broken, E - Replace

14,40



Wing R L, Chemical polution, 67 - Polish

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Chemical polution, LI - Repair and paint (complete)

220,18







Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete) 115,56



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Door R L, Scratch(es), Acceptable 0,00

No pictures to display