



AUDI A4: 1JEY634

Vinnumber:	WAUZZZ8K1FA062305	Versionname:	A4 AVANT Ultra 136PK
First Registrationdate:	28/11/2014	Fiscalpower:	
Expertise Mileage:	171618	Power Kw:	100
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	A12
Maintenance:	OVER 6000 KM:		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
TV/DVD screen R	Luggage cover	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	N.D.	Fr.R.	N.D.
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			190,00
Seat cover R L, Stain, Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Boot carpet, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Repaired, P - Check	0,00



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00

