


AUDI A4: 1GTU769

Vinnumber:	WAUZZZ8K4EA136945	Versionname:	A4 AVANT TDie 136PK
First Registrationdate:	28/04/2014	Fiscalpower:	
Expertise Mileage:	188210	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4213
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	CD
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2041,74
-------------------	----------------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Wing F R, Dent(s), LI - Repair and paint (complete)

220,18



Rear window, Scratch(es), E - Replace

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Chemical pollution, LI - Repair and paint (complete)

308,20



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), LI - Repair and paint (complete)

366,35




Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Windscreen, Stone chip(s), Windscreen repair

0,00



Bumper F, Crack, Le - Replace and paint

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

