


LU Audi a3 Sportback: HZ5634

Vinnumber:	WAUZZZ8V5HA042930	Versionname:	1.6 TDI 81KW DESIGN SPORTBACK
First Registrationdate:	1/12/2016	Fiscalpower:	
Expertise Mileage:	102204	Power Kw:	81
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3127
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 W LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	803,60
-------------------	--------

Wing R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Stone chip(s), Acceptable

0,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Tyre R R, Tear, Acceptable

0,00

