



BMW 3 BERLINE: 1PJL083

Vinnumber:	WBA8F91040K852535	Versionname:	2.0 316D (85KW) BERLINE
First Registrationdate:	14/07/2016	Fiscalpower:	
Expertise Mileage:	168970	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4513
Maintenance:	PLUS 17000 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Rear parking sensors
GPS storage	HD	
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT		0,00
-------------------	--	------

Door F R, Scratch(es), Acceptable		0,00
-----------------------------------	--	------



Wing R L, Scratch(es), Acceptable 0,00



Door F R, Repaired, P - Check 0,00



Bumper F, Scratch(es), Acceptable 0,00



Bumper R, Repaired, No repair 0,00



Step R, Scratch(es), Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00



Wing F R, Repaired, No repair 0,00



Door F L, Scratch(es), Acceptable 0,00



Windscreen, Repaired, P - Check 0,00



Roof, Dent(s), Acceptable 0,00



Wing R R, Repaired, No repair

0,00



Tailgate, Repaired, No repair

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Door R R, Repaired, P - Check

0,00

