



BMW 3 BERLINE: 1LKT392

Vinnumber:	WBA8C31010K686464	Versionname:	2.0 318D (100KW) BERLINE
First Registrationdate:	14/10/2015	Fiscalpower:	
Expertise Mileage:	132213	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	17000KM	Parking lot:	SHOWROOM
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			299,80
Door F R, Dent(s), Acceptable			0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Stone chip(s), Acceptable

0,00



Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Door F L, Scratch(es), Acceptable

0,00



Tailgate, Not original part, Sticker removal

25,00



Windscreen, Repaired, Acceptable

0,00

