



**BMW 1 HATCH: 1LTX133**

|                                    |                          |              |                        |
|------------------------------------|--------------------------|--------------|------------------------|
| Vinnumber:                         | <b>WBA1V91010V493051</b> | Versionname: | <b>1.5 116D (85KW)</b> |
| First Registrationdate:            | <b>3/12/2015</b>         | Fiscalpower: |                        |
| Expertise Mileage:                 | <b>119847</b>            | Power Kw:    | <b>85</b>              |
| Bodytype:                          |                          | Body color:  | <b>Black</b>           |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>         |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>       |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>              |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>A12</b>             |
| Battery functioning:               | <b>Yes</b>               |              |                        |
| Number of doors:                   | <b>5</b>                 |              |                        |
| Number of seats:                   | <b>5</b>                 |              |                        |
| Number head rests:                 | <b>5</b>                 |              |                        |
| Rims summer:                       | <b>Aluminium</b>         |              |                        |
| Category:                          | <b>Passenger Car</b>     |              |                        |
| Oil level:                         | <b>OK</b>                |              |                        |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                        |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/92 H LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>746,88</b> |
|-------------------|---------------|

|                                      |             |
|--------------------------------------|-------------|
| Roof, Chemical polution, 67 - Polish | <b>0,00</b> |
|--------------------------------------|-------------|



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Wing F L, Dent(s), Acceptable 0,00

*No pictures to display*

Roof, Dent(s), Acceptable 0,00

*No pictures to display*

Ignition key, Missing, E - Replace 150,00

*No pictures to display*