



BMW 2 ACTIVE TOURER: 1KVC243

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber: | WBA2B31030V542860 | Versionname: | 1.5 216D ACTIVE TOURER |
| First Registrationdate: | 10/07/2015 | Fiscalpower: | |
| Expertise Mileage: | 63651 | Power Kw: | 85 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3104 |
| Maintenance: | OVER 19000 KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Windows electric F | Central consol F |
| Windows electric R | Luggage cover |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Radio multimedia | No Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------------|-------|----------------------|
| | 205/60/16/92 V LightMetal | | | |
| Summer tyres: | Fr.L. | Hankook: 5 mm | Fr.R. | Hankook: 5 mm |
| | Re.L. | Hankook: 6 mm | Re.R. | Hankook: 6 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|---|---------|
| Total cost ex VAT | 1074,95 |
| Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 259,80 |



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

