



**BMW 3 GRAN TURISMO: 1LPP264**

|                                    |                          |              |                                      |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber:                         | <b>WBA3Y11040D902697</b> | Versionname: | <b>2.0 318D (100KW) GRAN TURISMO</b> |
| First Registrationdate:            | <b>6/11/2015</b>         | Fiscalpower: |                                      |
| Expertise Mileage:                 | <b>104316</b>            | Power Kw:    | <b>100</b>                           |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                         |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                       |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                     |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                            |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>LKW1</b>                          |
| Number of doors:                   | <b>5</b>                 |              |                                      |
| Number of seats:                   | <b>5</b>                 |              |                                      |
| Number head rests:                 | <b>5</b>                 |              |                                      |
| Rims summer:                       | <b>Aluminium</b>         |              |                                      |
| Category:                          | <b>Passenger Car</b>     |              |                                      |
| Oil level:                         | <b>OK</b>                |              |                                      |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                      |

**Options**

|                                |                                  |                      |                   |
|--------------------------------|----------------------------------|----------------------|-------------------|
| Radio CD                       |                                  | Central consol F     |                   |
| GPS storage                    | <b>HD</b>                        | Luggage cover        |                   |
| GPS storage                    |                                  | Rear parking sensors |                   |
| Windows electric F             |                                  | Type of Tow bar      | <b>No Tow bar</b> |
| Windows electric R             |                                  |                      |                   |
| Cruise Control                 |                                  |                      |                   |
| Steering wheel multifunctional |                                  |                      |                   |
| Radio multimedia               |                                  |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>      |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>      |                      |                   |
| Type of Lining                 | <b>Lining artificial leather</b> |                      |                   |
| Type of climate control        | <b>Autom climate control</b>     |                      |                   |

**Limited Technical Inspection**

|                     |               |                     |            |
|---------------------|---------------|---------------------|------------|
| Airco functioning   | <b>OK</b>     | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>NOT OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b>     | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b>     | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>     | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b>     | Transmission        | <b>OK</b>  |
|                     |               | Lighting            | <b>OK</b>  |
|                     |               | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>225/55/17/97 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                            | <b>Michelin: 3 mm</b> | Re.R. | <b>Michelin: 3 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>613,60</b> |
|-------------------|---------------|

|                         |             |
|-------------------------|-------------|
| Tires, Flat, Acceptable | <b>0,00</b> |
|-------------------------|-------------|



Wing R R, Dent(s), Acceptable 0,00



Alloy rim F L, Scratch(es), Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), Acceptable 0,00



Door F R, Dent(s), Acceptable

0,00



Seat cover R L, Incomplete, Acceptable

0,00



Seat cover F L, Damaged, Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Dent(s), Acceptable

0,00

*No pictures to display*

Tailgate, Dent(s), Acceptable

0,00

*No pictures to display*