



BMW 3: 1HPT585			
Vinnumber:	WBA3D11050P700168	Versionname:	3 BER 318d 136PK
First Registrationdate:	8/09/2014	Fiscalpower:	
Expertise Mileage:	122870	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1323
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Type of Tow bar	No Tow bar
GPS storage			
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 2 mm	Re.R.	Continental: 2 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	543,44
Door F R, Dent(s), PDR - Paintless dent repair	63,00



Door R R, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Seat cover F L, Worn, Acceptable

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Door panel F R, Hole, Smart repair

110,64



Seat cover F R, Worn, Acceptable

0,00



Windscreen, Stone chip(s), Acceptable 0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display