



BMW 3 TOURING: SY7778

Vinnumber:	WBA8H91060K869671	Versionname:	2.0 320D (140KW) TOURING
First Registrationdate:	11/11/2016	Fiscalpower:	
Expertise Mileage:	135009	Power Kw:	140
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2324
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	225/55/16/95 H LightMetal			
	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	824,32
--------------------------	---------------

Alloy rim F R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Door panel R L, Tear, Smart repair 110,64



Windscreen, Stone chip(s), Acceptable 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08

