



FORD GRAND C-MAX: 1KHZ616

Vinnumber:	WFOHXXGCBHFD66673	Versionname:	1.6 TDCI TREND STYLE
First Registrationdate:	8/05/2015	Fiscalpower:	
Expertise Mileage:	95278	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1333
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	839,28
-------------------	---------------

Mirror side blinker L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Maintenance book, Missing, E - Replace	0,00
--	-------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Floor covering R, Dirty, Cleaning

25,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

404,20



Backrest cover F R, Worn, P - Check

0,00



Floor covering F L, Worn, P - Check

0,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover R L, Stain, Cleaning

25,00



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Stain, Acceptable

0,00

No pictures to display