



BMW i3: 1PJK548

Vinnumber:	WBY1Z21080V304814	Versionname:	
First Registrationdate:	6/11/2014	Fiscalpower:	
Expertise Mileage:	103409	Power Kw:	75
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Electric	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1425
Number of doors:	5		
Number of seats:	4		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	155/70/19/84 Q LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1635,44
Interior, Dirty, Cleaning	100,00



Bumper F M, Scratch(es), Smart repair

110,64



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display


Rear window, Scratch(es), E - Replace

420,00



Windscreen, Scratch(es), E - Replace

560,64






Roof pillar R, Bad repair, Acceptable

0,00



Wing R R, Bad repair, Acceptable

0,00




Door R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Worn, Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper cover R M, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display