



**MERCEDES C BREAK: 1LSN366**

Vinnumber:	<b>WDD2052421F285762</b>	Versionname:	<b>2.0 C 200 EXCLUSIVE</b>
First Registrationdate:	<b>24/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>102399</b>	Power Kw:	<b>135</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1310</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Rear parking sensors	
Type of GPS	<b>GPS big screen color</b>	Type of Tow bar	<b>Tow bar fixed</b>
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/50/17/94 W LightMetal</b>			
Summer tyres:	Fr.L. Goodyear: 4 mm	Fr.R. Goodyear: 4 mm	
	Re.L. Goodyear: 4 mm	Re.R. Goodyear: 4 mm	

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>523,60</b>
Bumper F, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Rear window, Scratch(es), E - Replace 0,00



Boot carpet, Chemical polution, E - Replace 100,00



Alloy rim F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R L, Scratch(es), Acceptable 0,00

*No pictures to display*