



MERCEDES C BREAK: 1PRU942

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnumber: | WDD2052361F440067 | Versionname: | 1.6 C 180 D EXCLUSIVE |
| First Registrationdate: | 1/09/2016 | Fiscalpower: | |
| Expertise Mileage: | 154810 | Power Kw: | 85 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4630 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Seats electric F L | |
| Windows electric F | | Seats electric F R | |
| Windows electric R | | Sun Roof electric | |
| Cruise Control | | Central consol F | |
| Steering wheel multifunctional | | Front parking sensors | |
| Seats F heated | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting LED | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 225/50/17/94 Y LightMetal | | | | |
| Summer tyres: | Fr.L. | Semperit: 5 mm | Fr.R. | Semperit: 5 mm |
| | Re.L. | Semperit: 5 mm | Re.R. | Semperit: 5 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|---|---------------|
| Total cost ex VAT | 401,80 |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

