



PEUGEOT 2008; 1LFD962

Vinnumber:	VF3CUBHXYFY104416	Versionname:	1.6 BLUEHDI 85KW S/S ACTIVE
First Registrationdate:	11/09/2015	Fiscalpower:	
Expertise Mileage:	118721	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3701
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/60/16/89 H LightMetal				
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	848,00
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Side window trim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Stone chip(s), Acceptable

0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair

63,00



Windscreen, Scratch(es), Acceptable

0,00



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Wing R L, Repaired, Acceptable

0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair

162,00




Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

370,00





Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display