



**LU Mercedes glc: FL0376**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>WDC2539051F019185</b> | Versionname: | <b>2.1 GLC 220 D 4MATIC EXCLUSIVE AUTO</b> |
| First Registrationdate:            | <b>19/01/2023</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>120661</b>            | Power Kw:    | <b>125</b>                                 |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                                |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                             |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                  |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>2501</b>                                |
| Battery functioning:               | <b>Yes</b>               |              |  |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Front parking sensors            |
| Cruise Control                 | Rear parking sensors             |
| Steering wheel multifunctional |                                  |
| Type of headlighting           | <b>Headlighting LED</b>          |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                          |       |                          |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
|               | <b>235/60/18/92 MS LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                             | <b>Continental: 5 mm</b> | Fr.R. | <b>Continental: 5 mm</b> |
|               | Re.L.                             | <b>Continental: 6 mm</b> | Re.R. | <b>Continental: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|   |      |
|---|------|
| Total cost ex VAT                               | 0,00 |
| Bumper R, Scratch(es), Acceptable               | 0,00 |
| <i>No pictures to display</i>                   |      |
| Alloy rim R L polished, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>                   |      |
| Wing trim R R, Bad repair, Acceptable           | 0,00 |



Wing R L, Dent(s), Acceptable

0,00

*No pictures to display*