



**MERCEDES GLA: NB6862**

Vinnumber:	<b>WDC1569081J549428</b>	Versionname:	<b>GLA 200 d Business Solution</b>
First Registrationdate:	<b>16/08/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>41988</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1223</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/17/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Vredestein: 4 mm</b>	Fr.R.	<b>Vredestein: 4 mm</b>
	Re.L.	<b>Vredestein: 5 mm</b>	Re.R.	<b>Vredestein: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	150,00
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Repaired, Acceptable	0,00



Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	