



**PEUGEOT 308: 1HZV347**

Vinnumber:	<b>VF3LCBHXHES256495</b>	Versionname:	<b>308 SW BlueHDi Allure STT 116PK</b>
First Registrationdate:	<b>12/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>122524</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2415</b>
Maintenance:	<b>14400KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>310,00</b>
-------------------	---------------

Rearview mirror housing L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------



Rearview mirror housing R, Scratch(es), Acceptable

0,00



Alloy rim F L polished, Scratch(es), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Alloy rim F R polished, Scratch(es), I - Repair

155,00



Door F L, Scratch(es), Acceptable

0,00



Door F R, Dent(s) and scratch(es), Acceptable

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00



Alloy rim R L polished, Scratch(es), I - Repair

155,00

