



RENAULT CLIO: 1LRG221

Vinnumber:	VF15R0J0A53968407	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	13/11/2015	Fiscalpower:	
Expertise Mileage:	76019	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4620
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1881,68
Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)	344,40



Outer door handle F L, Missing, E - Replace 20,00



Seat cover F L, Stain, Acceptable 0,00

No pictures to display

Dashboard, Scratch(es), Smart repair 110,64



Wheel cover R L, Scratch(es), E - Replace 24,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Wing F L, Deformed / Strained, Forfeit 48,00



Door moulding Lower R R, Scratch(es), E - Replace 96,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 392,40




Door frame F L, Dent(s), It - Spot repair 127,56



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover F R, Scratch(es), E - Replace 24,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display