



**RENAULT CLIO: 1LSD420**

Vinnumber:	<b>VF15R0J0A53968412</b>	Versionname:	<b>1.5 ENERGY DCI 90E EXPRESSION</b>
First Registrationdate:	<b>20/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>115649</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4633</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/92 V Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>489,44</b>
Rocker panel inner F R, Dent(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door R R, Dent(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wheel cover F L, Scratch(es), E - Replace	<b>24,00</b>



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler R, Scratch(es), E - Replace 148,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Roof, Chemical polution, Acceptable 0,00

No pictures to display

Bonnet, Bad repair, Acceptable 0,00



Wheel cover F R, Scratch(es), E - Replace 24,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 50,00



Engine protective plate, Deformed / Strained, E - Replace 74,00

