



RENAULT CLIO: 1LTN517

Vinnumber:	VF15R0J0A54168223	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	1/12/2015	Fiscalpower:	
Expertise Mileage:	67376	Power Kw:	66
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3308
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/92 T Steel				
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	480,32
Door F R, Bad repair, Acceptable	0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Rear spoiler, Chemical pollution, 67 - Polish 0,00

No pictures to display

Floor covering F L, Hole, Smart repair 64,32



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Broken, E - Replace 24,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 320,00



Bumper F, Dent(s) and scratch(es), Acceptable 0,00



Wheel cover R R, Scratch(es), E - Replace 24,00



Wing F R, Bad repair, Acceptable 0,00



Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bad repair, Acceptable 0,00



Wheel cover F R, Scratch(es), E - Replace 24,00



Wheel cover F L, Scratch(es), E - Replace 24,00

