



**RENAULT MEGANE GRANDTOUR: 1NAE540**

Vinnumber:	<b>VF1KZ0C0H54464492</b>	Versionname:	<b>1.5 ENERGY DCI 95 TOMTOM? EDITION</b>
First Registrationdate:	<b>4/01/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>149298</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>LKW1</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/92 H Steel</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>2844,89</b>
Bumper F, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>



Rear window, Scratch(es), E - Replace 0,00



Rocker panel inner F L, Scratch(es), Forfeit 115,56



Bumper R, Scratch(es), Smart repair 110,64



Door frame F L, Scratch(es), It - Spot repair 115,56



Rear bulkhead lining, Scratch(es), Smart repair 110,64



Bonnet, Dent(s), LI - Repair and paint (complete) 290,08



Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Door F R, Dent(s), LI - Repair and paint (complete) 318,35



Rocker panel inner R L, Scratch(es), Forfeit 115,56



Wheel cover F R, Crack, E - Replace 30,00



Wheel cover F L, Crack, E - Replace 30,00



Headlight L, Broken, E - Replace

396,00



Maintenance, Maintenance, Execute

0,00



Rearlight R, Crack, E - Replace

114,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

380,20



Dashboard, Glue residues, Cleaning

25,00

