



RENAULT Kangoo Express: 1FWL748

Vinnumber:	VF1FW18B549945959	Versionname:	KANGOO EXPR.B/F Gr.Confort 90PK
First Registrationdate:	19/11/2013	Fiscalpower:	
Expertise Mileage:	152046	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	LCV16
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1790,08
-------------------	----------------

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------

<i>No pictures to display</i>	
-------------------------------	--

Interior, Dirty, Acceptable	0,00
-----------------------------	-------------

<i>No pictures to display</i>	
-------------------------------	--

Trunk door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	410,02
---	---------------





Bumper R, Scratch(es), Acceptable 0,00

No pictures to display


Trunk door R L, Dent(s), LI - Repair and paint (complete) 410,02



Bodywork, Dirty, P - Check 0,00



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) 457,13



Windscreen, Stone chip(s), Windscreen repair 58,80



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 279,15



Bumper F, Scratch(es), Smart repair 110,64



Seat cover F L, Hole, Smart repair

64,32



Bodywork, Not original part, Sticker removal

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display