



TOYOTA RAV4: 1NJZ912

Vinnumber:	JTMWRREVX0D001187	Versionname:	2.5 VVT-I HYBRID BUSINESS PLUS CVT AUTO
First Registrationdate:	8/03/2016	Fiscalpower:	145
Expertise Mileage:	115704	Power Kw:	145
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2513
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/65/17/102 H LightMetal			
Winter tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1908,73
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Roof, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Luggage space cover, Missing, E - Replace

240,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Repaired, Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



