



VOLKSWAGEN GOLF VII: 1LLT466

Vinnumber:	WVWZZZAUZGP040535	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	22/10/2015	Fiscalpower:	
Expertise Mileage:	70383	Power Kw:	81
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3622
Maintenance:	UITVOEREN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 M-S LightMetal				
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	711,60
Door R R, Dent(s), Acceptable	0,00



Seat cover R L, Stain, Cleaning

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Dent(s), Acceptable

0,00



Engine, Maintenance, Execute

0,00



Alloy rim F L polished, Scratch(es), Acceptable

0,00



Roof, Hail damage, Forfeit hail (heavy)

0,00



Alloy rim R R polished, Scratch(es), Acceptable

0,00



Ignition key, Missing, E - Replace

150,00



Seat cover F R, Stain, Cleaning

25,00



Wing F R, Bad repair, LI - Repair and paint (complete)

0,00



Trunk lid covering R, Scratch(es), Acceptable 0,00



Seat cover R R, Dirty, Cleaning 25,00



Bumper F, Bad repair, LI - Repair and paint (complete) 211,80



Alloy rim F R polished, Scratch(es), I - Repair 0,00



Seat cover F L, Stain, Cleaning 25,00



Rear window, Not original part, Remove lettering 0,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00

