



SKODA SUPERB COMBI: 1RVH948

Vinnumber:	TMBJH9NP7H7527804	Versionname:	2.0 CRTDI 110KW DSG6 STYLE
First Registrationdate:	10/03/2017	Fiscalpower:	
Expertise Mileage:	201226	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	A12
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats R heated
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/92 MS LightMetal				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1072,18
Roof, Hail damage, PDR - Hail			0,00



Roof pillar R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	310,50



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Bonnet, Dent(s), LI - Repair and paint (complete)	338,08
---	--------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Roof pillar L, Dent(s), Acceptable

0,00

No pictures to display