



Volkswagen Golf: 1KJX487

Vinnnumber:	WVWZZZAUZFW612152	Versionname:	
First Registrationdate:	18/05/2015	Fiscalpower:	
Expertise Mileage:	100731	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1225
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2173,77
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)	115,56



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Engine protective plate, Deformed / Strained, E - Replace 74,00




Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80




Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Repaired, Acceptable 0,00

No pictures to display

Windscreen, Scratch(es), E - Replace 487,20



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00



Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display