



**TOYOTA RAV4: 1RXR192**

Vinnumber:	<b>JTMWRREV40D034993</b>	Versionname:	<b>2.5 VVT-i Hybrid Comfort CVT</b>
First Registrationdate:	<b>21/03/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>161307</b>	Power Kw:	<b>114</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>A12</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar removable</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/65/17/102 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 8 mm</b>	Fr.R.	<b>Michelin: 8 mm</b>
	Re.L.	<b>Yokohama: 7 mm</b>	Re.R.	<b>Yokohama: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>597,84</b>
-------------------	---------------

Internal Boot Lining R, Scratch(es), Acceptable	<b>0,00</b>
---	-------------

*No pictures to display*

Trunk lid covering R, Scratch(es), Smart repair	<b>110,64</b>
---	---------------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Internal Boot Lining L, Scratch(es), Acceptable	<b>0,00</b>
---	-------------

Internal Boot Lining L, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace

487,20



Boot carpet, Scratch(es), Acceptable

0,00

