



SKODA SUPERB COMBI: 1JNP117

Vinnumber:	TMBJJ73TXF9039473	Versionname:	1.6 CRTDI 77KW DSG 7 ELEGANCE
First Registrationdate:	26/01/2015	Fiscalpower:	
Expertise Mileage:	153802	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4407
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar removable
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/40/18/92 MS LightMetal				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			748,80
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)			95,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00



Bonnet, Repaired, Acceptable 0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bodywork, Not original part, Forfeit 25,00



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tyre R R, Tear, E - Replace 132,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00

