



**VOLKSWAGEN PASSAT VARIANT: 1LTP358**

Vinnumber:	<b>WVWZZZ3CZGE126090</b>	Versionname:	<b>2.0 TDI VARIANT HIGHLINE</b>
First Registrationdate:	<b>1/12/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>87599</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Light Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2703</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/55/17/94 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1076,28</b>
Compressor, Missing, E - Replace	<b>0,00</b>



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F L, Missing, E - Replace 14,40



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F R, Missing, E - Replace 14,40



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Scratch(es), E - Replace 0,00





Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Deformed / Strained, Acceptable	0,00



Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tyre repair kit, Missing, E - Replace	210,53



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

