



VOLVO S60: 1JAY947

Vinnumber:	YV1FS8488F2351966	Versionname:	S60 BER D2 Kinetic Powersh.115PK Aut.
First Registrationdate:	20/11/2014	Fiscalpower:	
Expertise Mileage:	80284	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4206
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/50/17/96 V LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			558,56
Bumper F L, Scratch(es), It - Spot repair			115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

