



SKODA OCTAVIA COMBI: 1LGR145

Vinnumber:	TMBJF7NE6G0074775	Versionname:	1.6 CRTDI 66KW GREENTEC AMBITION
First Registrationdate:	23/09/2015	Fiscalpower:	
Expertise Mileage:	174843	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1230
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			75,00
Seat cover R L, Stain, Cleaning			15,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Luggage space cover, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Missing, E - Replace 30,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00



Bumper F, Broken, Le - Replace and paint 0,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Scratch(es), Acceptable 0,00

No pictures to display