



AUDI A1 SPORTBACK: 1TLK802

Vinnumber:	WAUZZZ8XXJB044089	Versionname:	1.0 TFSI ultra 60kW
First Registrationdate:	7/12/2017	Fiscalpower:	
Expertise Mileage:	37318	Power Kw:	60
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	PARKING GARAGE
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H LightMetal			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1128,26
-------------------	----------------

Tailgate, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	246,56
---	---------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Bonnet, Chemical polution, LI - Repair and paint (complete)

232,06



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), Acceptable

0,00



Door R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

385,20



