



AUDI A3 BERLINE: 1KXZ855

Vinnumber:	WAUZZZ8VXG1019593	Versionname:	1.6 TDI 81KW AMBIENTE
First Registrationdate:	29/07/2015	Fiscalpower:	
Expertise Mileage:	74393	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2830
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1950,51
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Ignition key, Missing, E - Replace

150,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rear window, Scratch(es), E - Replace

0,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Xenon headlight L, Scratch(es), 67 - Polish

25,00



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00

